

INFORMATION & INSTRUCTIONS

General Use

Decorative use only on candles, glass, metal, wood and soap

Printing Equipment

Water Slide - WT works in new Non-Oil Color Laser Copiers/Printers
Water Slide - WT will also work in fuser oil type Copiers/Printers

What you will need

- Item to be imaged ie: candle, glass etc.
- Imaged WT Transfer Paper
- Bowl large enough to dip chosen object into
- Liquid dish soap
- Plastic– either plastic wrap or plastic bag
- 1 sheet of plain bond paper

Printing

- ▶ If using a Color Copier, Black and White Copier or Thermal Printer:
 - Place WT Paper in bypass tray, positioned to image onto glossy side
 - Copy/Print in Plain Paper/Standard Mode.
 - Don't copy/print **Mirror Image**.
- ▶ If using Oil based felt pens or Acrylic color paints:
 - Draw on Glossy side of WT transfer Paper. Let image dry completely before proceeding.

Application Instructions

- Trim imaged WT as close as possible to image without cutting into image, using scissors/ exacto knife.
- Fill suitable size bowl with warm water and add about 5%-10% liquid dish soap to bowl of water.
- Wet the item to be imaged in the bowl of water and set to one side.
- Place imaged WT in bowl of soapy water for 5-10 seconds.
- Put wet WT on plastic, image face down, and cover with plain sheet of paper to take off excess water.
- Remove plain paper.
- Gently remove paper backing from WT Transfer Paper.
- Pick up plastic with imaged decal/film laying on top and place on candle, glass or other item.
- Gently remove plastic.
- With sponge or finger correct position of decal and take out any air bubbles.
- Let dry for at least 1 hour before handling.

NOTE: For extra durability on candles we suggest using a glue stick to help adhere the WT Transfer Paper or heating the candle with a blow dryer to soften the wax before applying the transfer.